



TECHNICAL BULLETIN TECH-11-2022

PSA 1.2L – 870248-5002S TURBOCHARGER REPLACEMENT

NOVEMBER 2022


Garrett
ADVANCING MOTION

PSA 1.2L – 870248-5002S TURBOCHARGER REPLACEMENT

Dear Customer,

Please note that this Tech bulletin is to inform you of a mistake that was recently made in our online catalogue in specifying the wrong turbocharger PN 901680-5002S as replacement of turbochargers PN 887157-5001S & PN 870248-5002S, which is not a direct service replacement for the following reason explain below.


- TC 901680-5002S is a standalone turbocharger as it doesn't use the e-RCV valve on the compressor housing.



- The correct direct service replacement is as follow: TC PN 870248-5002S replaced by TC PN 887157-5001S as they are using the same e-RCV.

TC PN 870248-5002S → Replaced by → PN 887157-5001S

e-RCV (Electric – Recirculation Compressor Valve)



Sorry for this inconvenience and we now confirm that our online catalogue has now been corrected, hence please distribute this information to all in your company who may need it.

Best Regards,

IAM Technical Specialist support team.

Garrett – Advancing Motion

